




Williams Drive Study - Challenges & Recommendations

Pedestrian/Bicycle Improvements



CAUSES


- Sidewalks are neither continuous nor desirable
- Lack of dedicated bicycle paths and lanes
- Existing and new driveways, speeds, and site design are not conducive to non-vehicular modes of transport



SOLUTIONS

- Focus attention through Capital Improvement Program (CIP) planning
- Provide incentives/grants
- Consider on- and off-street bicycle facility improvements where appropriate

Bicycle Connections



Pedestrian Crossings and Gaps

