Representative photographs of APE



Figure 1. View of Riverhaven Drive and FM 971 (Facing North)



Figure 2. View of Riverhaven Drive and FM 971 (Facing West)



Figure 3. View of Riverhaven Drive (Facing East)



Figure 4. View from Riverhaven Drive Facing Towards San Gabriel Park (Facing South)



Figure 5. View of FM 971 from Riverhaven Drive (Facing Northeast)



Figure 6. View of land between FM 971 and Riverhaven Drive (Facing East)



Figure 7. View of FM 971 near Southwestern End of APE (Facing Northwest)



Figure 8. View of Frisbee Golf Course South of Riverhaven Drive (Facing Northeast)



Figure 9. View of San Gabriel Park from Riverhaven Drive (Facing Southeast)



Figure 10. View of Parcel between FM 971 and Riverhaven Drive (Facing West)



Figure 11. View of Parcel between FM 971 and Riverhaven Drive (Facing North)



Figure 12. View of Parcel between FM 971 and Riverhaven Drive (Facing East)



Figure 13. View of Intersection of FM 971 and Morrow Street (Facing Northwest)



Figure 14. View of FM 971 from Deep Creek Road (Facing Southwest)



Figure 15. View of FM 971 from Deep Creek Road (Facing Northeast)



Figure 16. View of FM 971 from Prairie Springs Lane (Facing Southwest)



Figure 17. View of FM 971 from Prairie Springs Lane (Facing Northeast)



Figure 18. View of FM 971 and NE Inner Loop near Cooper Elementary School (Facing Southwest)



Figure 19. View of FM 971 and NE Inner Loop near Cooper Elementary School (Facing Northwest)



Figure 20. View of CR 152 and FM 971 (Facing Southwest)



Figure 21. View of CR 152 and FM 971 (Facing East)



Figure 22. View of Georgetown Memorial Cemetery from CR 152 (Facing West)



Figure 23. View of FM 971 toward NE Inner Loop Road (Facing Southwest)



Figure 24. View of FM 971 near Parkside Crossing Residential Subdivision (Facing Southwest)



Figure 25. View of Drainage Structures Adjacent to FM 971 (Facing Northeast)



Figure 26. View of Morrow Street along Front of Guadalupe Cemetery (Facing Northeast)



Figure 27. View of Guadalupe Cemetery Entrance on Morrow Street (Facing Northwest)



Figure 28. View of Southwestern Half of Guadalupe Cemetery from Entrance (Facing West-Southwest)



Figure 29. View of Northeastern Half of Guadalupe Cemetery from Entrance (Facing West-Northwest)



Figure 30. View along Southwestern Edge of Back (Northwestern) Boundary of Guadalupe Cemetery (Facing Southwest)



Figure 31. View along Northeastern Side of Back (Northwestern) Boundary of Guadalupe Cemetery (Facing Northeast)



Figure 32. View of Northern Corner of Guadalupe Cemetery (Facing Northeast)



Figure 33. View of Exterior of Guadalupe Cemetery from Proposed New FM 971 ROW (Facing Southeast)



Figure 34. View of Modern Ground Surface within Proposed New ROW Northwest of Guadalupe Cemetery (Facing Southwest)



Figure 35. View of Mapped Location of Site 41WM991 within Intersection of FM 971 and NE Inner Loop (Facing Northeast)



Figure 36. View of Mapped Location of Site 41WM1015 within Intersection of FM 971 and SH 130 (Facing Northeast)